

[illegible]

Fig. 2




Fig. 3




Fig. 4




Fig. 1 is a schematic diagram of a mechanical assembly in cross-section. It shows two vertical shafts, 21 and 22, passing through a housing 24. The shafts are supported by bearings 23 and 27. The shaft 21 has a seal 26 at the bottom, and the shaft 22 has a seal 25. The assembly is mounted on a base 50 with a central support 51 and side supports 52, 53, and 54. The diagram includes various cross-hatching patterns to represent different materials and components.

Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10

